

Appl. No: 10/692,532

Reply to Formalities Letter of Sept. 28, 2004

Replacement sheet





FIGURE 1 - PRIOR ART






Figure 2

Figure 3 - Message Routing




Figure 4 - Transceiver Routing




Figure 5 - Sensor Data Routing





Figure 6 - Transceiver Synchronization






Fig. 7. Diagram of a soil probe sensor node

Figure 8 - Separable Probe Body  
TOP PART 850






Figure 9




Figure 10 - Configuration and Dimensions of Probe Body





Figure 10A




Figure 10B





Figure 11 - Probe Shapes



### Figure 12 - Occupancy Detection




Figure 13 - Common Line Control





Figure 14



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**